

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION I

J.F. KENNEDY FEDERAL BUILDING, BOSTON, MASSACHUSETTS 02203-2211

May 9, 1989



SEMS DocID

621113

Harish Panchal
DEQE
Division of Solid

Division of Solid and Hazardous Waste One Winter Street
Boston, Massachusetts 02108

RE:

Site Investigation (SI)

Vitale Flyash Pit L.P. Henderson Road Beverly, Massachusetts

Dear Mr. Panchal:

The following are my comments for the Vitale Flyash Pit SI which was submitted in partial fulfillment of the Multi Site Cooperative Agreement:

page	<u>paragraph</u>	<u>Comment</u>
1	1	-Last line contains a typo.
1	2	-Please refer to my previous correpondence relative to E.P. Toxicity testing at CERCLA sites.
5	1	-Did any past removal sampling occur when the tanks was removed in 1987?
5	4	-Provide an explanation for the magnetometer anomalies.
		-See my previous comments regarding E.P. Toxicity.

General Comments

- 1. Additional discussion should be provided pertaining to the relationship of the Vitale Flyash, Casco Chemical, and Airport Sites.
- 2. The analytical results could have been presented in tabular form for easier reading. Detection limits and CERCLA inorganic analysis should be included.

3. Due to the migration of the flyash from the site into Wenham Lake I need inorganic analysis of the arch prior to crediting this product as a SI deliverable. Ash

If you have any questions or require clarification of my comments please contact me at (617) 573-9697.

Sincerely,

Michael Nalipinski

Massachusetts State Coordinator

cc: Carl Deloi, Chief

Michael Nalgarita

Liz Callahan, DEQE-Woburn